

# Digital Weighing Indicator SI 300

# **Instruction Manual**





## CONTENTS

1.	Before Installation	 3 Page
2.	Introduction	 4 Page
3.	Specification	 5 Page
	3-1. Specification	 5 Page
	3-2. Front Panel	 6 Page
	3-3. Connector	 8 Page
	3-4. Composition	 8 Page
4.	Installation	 9 Page
	4-1. Dimension & Cutting Size	 9 Page
	4-2. Installation Components	 10 Page
5.	Set up	 11 Page
	5-1. Set Up mode	 11 Page
	5-2. TEST Weight Calibration Mode	 12 Page
	5-3. Simulating Calibration Mode	 14 Page
	5-4. F-FUNCTION Setting	 16 Page
	5-5. Test Mode	 22 Page
6.	Interface	 24 Page
	6-1. Serial Interface	 24 Page
	6-2. Serial Print	 33 Page
7.	Error & Treatment	 34 Page
Wa	arrantee Certificate	 37 Page

## **1. BEFORE INSTALLATION**

#### **Caution / Warning Marks**

	This mark warns the possibility to arrive death or serious injury
Warning	in case of wrongly used.
٨	This mark cautions the possibility to arrive serious human body
Caution	injury or product lose in case of wrongly used.

#### **Copy Rights**

- 1. All Right and Authority for this Manual is belonged to SEWHA CNM CO., LTD.
- 2. Any kinds of copy or distribution without permission of SEWHA CNM CO., LTD. will be prohibited.
- 3. This manual may be changed as the version is upgraded, without previous notice.

#### Inquiries

If you have any kinds of inquiries for this model, please contact your local agent or Head Office.

Head Office : SEWHA CNM CO., LTD.

Website : http://www.sewhacnm.co.kr

Email : sales@sewhacnm.co.kr

## 2. INTRODUCTION

#### Introduction

Thank you for your choice of this SI300 Industrial Digital Weighing Indicator.

This SI300 model is high-performance weighing Indicator.

Please review and learn this instruction Manual and enjoy your process efficiency

with "SI 300" Weighing Indicator.



- 1. Don't drop on the ground and avoid serious external damage on item.
- 2. Don't install under sunshine or heavy vibrated condition.
- 3. Don't install place where high voltage or heavy electric noise condition.
- 4. When you connect with other devices, please turn off the power of item.
- 5. Avoid from water damage.
- 6. For the improvement of function or performance, we can change item specification without previous notice or permission.
- 7. Item's performance will be up-dated continuously base on previous version's performance.

#### Features

- 1. SI 300 model is the standard 1/8 DIN SIZE and compact enough, so it is easy to install.
- 2. It has wide range of DC Input.
- 3. Front panel is covered with Polycarbonate film, strong against dust and water.
- 4. RS-422/485 serial port standard installed,

## **3. SPECIFICATION**

## 3-1 Specification

Content			Specification	
	External Resolution		1/20,000	
	Internal Resolution		1/2,097,152 (±1,048,576)	
	Input	Sensitivity	0.1µV/V	
	Max. Signa	l Input Voltage	3.0 mV/V	
	Load ce	ell Excitation	DC +5V	
Performance	A/D Conv	ersion Method	Sigma-Delta	
	Deci	mal Point	0, 0.0, 0.00, 0.000	
	Duitt	Offset	10PPM/°C	
	Driit	Span	10PPM/°C	
	Linearity		0.001% of Full Scale	
	Analogue Sampling(sec)		60times / sec	
Environment	Operating Temperature Range		-10°C ~ +40°C [14°F ~ 104°F]	
Linvironment	Operation Humidity Range		40% ~ 85% RH, Non-condensing	
	Calibration Mode		Test Weight Calibration Mode	
			Simulation Calibration Mode	
Function	Display		7segment 6 digit, 1 inch	
			Red Color FND	
	Key Pad		6EA Key including CAL key	
			Data Transference	
Comm	Serial Interface		Command Mode	
			Serial Printer Mode	
Power	Power AC100V ~ AC 24		40V (50/60Hz)	
<b>Size</b> 190mm(W) x 124mm(H) x 122mm(D)		Weight : 2.0kg		

## 3-2. Front Panel

## 3-2-1 Front Panel (Display / Key Pad)



#### 3-2-2. State Lamp

Display	Meaning	
STEADY	When the weight is "STEADY", Lamp is ON.	
ZERO	When the current weight is "ZERO", Lamp is ON.	
TARE	"TARE" function is set, Lamp is ON.	
HOLD	"HOLD" function is set, Lamp is ON.	
TyD	When the Indicator transmits Serial communication data (Print data),	
	Lamp is ON.	
<b>RxD</b> When the Indicator receives Serial communication data, Lamp		
F	When the "F" key is working, Lamp is ON.	

#### 3-2-3. Key Operation

ZERO	<ol> <li>Normal Mode : Make Weight value as Zero. (F07, F08 setting)</li> <li>Calibration Mode : Cancel the value or move to previous step.</li> </ol>
	1.Normal Mode : Set the TARE Function .(F09 setting)
	1 time input : "TARE", 2 times input : "TARE Reset"
	(When "HOLD" or weight value is ZERO, then this key doesn't work.)
	2.Calibration Mode : Move to left
	3.F-Function setting : Move to left
	4.Test Mode 1 : Analog value check mode
	1. To set the "HOLD" Function (refer F10) [1 <sup>st</sup> input : "HOLD", 2 <sup>nd</sup> input : "HOLD
	Reset" ]
HOLD	2.Calibration Mode : Move to right
	3.F-Function setting : Move to right
	3. Under "SETUP" Mode, Enter into the "Calibration" Mode.
	4.Test Mode 1 : Analog Variation value check mode
	1. Normal Mode : Print out (refer F38, F32)
	2.Calibration Mode :Increase set value
DDINIT	3.F-Function setting : Increase set value
	4. Set up Mode : Enter Test Mode.
	st If the printer is installed, under "F01-01 setting, when you press this key the current
	valued is increased. And the current weight is saved and print out, altogether. (Refer to
	CH.5-4)
E	1. Press this key 4times, within 2secs, enter "SET-UP" mode. 2.F-Function setting : Save the value go to next step

•Setup Mode :It is a mode can SET UP the calibration, Function of SI300. (refer to CH5. SET UP)

#### 3-2-4. Hot key (with F key)

Continuous "TARE" setting (From the second TARE setting, use this key)
If the Printer is installed, You can print out the "Grand-total data". (GRAND-total data can be checked though Print output).
Manual delete the grand total data

Max. accumulated weighing count : 999,999times Over 999,999times  $\rightarrow$  return to "0" time Max. accumulated weight display : 999999999 (g, kg, ton)

Over 999,999,999 (g, kg, ton)  $\rightarrow$  return to "0" (g, kg, ton)

## 3-3. Connector





#### 3-4. Composition

SI 300	AC Power Cable	Side Bolt	Terminal Pin	Manual
Ender Contraction of the second secon				E State

## 4. INSTALLATION

## 4-1. External Dimension & Cutting Size

External Dimension (unit: mm)

Front View











## 4-2 Load cell Installation

Load Cell Wire Connection (In case of SEWHACNM's Load cell) It depends on the manufacturer of load cell, please check the specification.



#### Load Cell Installation

- 1. You can connect Max. 8pcs of same capacity Load cells at once. (350  $\Omega$ )
- 2. You have to make horizontal balance on the ground.
- 3. If you install more than 2pcs of load cells, use Summing box and adjust output signal difference as minimum. It can make wrong weighing process caused by each load cell's variation.
- 4. If there is some temperature difference around Load cell, it can cause wrong weight measurement.
- 5. Don't do Welding job or Arc discharge around installation place. But, there is no choice, please disconnect power cable and Load cell cable.
- 6. If you measure static electricity material, please make earth between down part and up part of Load cell.
- 7. Under set up the Load cell, if EXC+ and EXC- have a short circuit, It may cause damage in the indicator.(specially analogue board)
- 8. If you connect other wires to Load cell terminal wrongly, it may cause damage in the analogue board.
- 9. Before connecting the load cell cable you have to power off and be sure to connect the cable to the terminal correctly.
- 10. Do not weld near the load cells , Indicators or other devices.



### 5-1. Adjusting "ZERO" Balance (Calibration)

Adjust weight balance between "Real weight" on the load cell(Weight Part) and "Displayed weight of Indicator". When you replace LOAD CELL or Indicator, you have to Calibrate process once again.

(When you start calibration mode, TARE, HOLD & PRINT function is reset.)



• Default is no password. Displaying "P-W" means the password is activated. Please input your pass word.

## 5-2 Test Weight Calibration Mode (Using test weight)

#### 5-2-1. Starting Test Weight Calibration Mode



### 5-2-3. "Decimal Point" and "Digit / Division" Value



#### 5-2-4. Measuring the "DEAD" Weight of Weighing Scale.

dEAd	When "DEAD" is displayed, press		
	Dead weight of scale part automatically.		
	Indicator will search "DEAD weight" during 10~20 seconds to find the best		
	condition		

\* To guarantee the preciseness, DEAD weight calculation (CAL00~CAL09) will be operated twice when resolution (Division value /Max capacity value) is less than 1/10,000.

In this step, if there is some force or vibration on weighing scale, and unstable condition will be continued, **"ErrorA"** will be display, and "DEAD value" will not be calculated.

Please remove all the force or vibration and process it again.

#### 5-2-5. Input Test Weight value and Calculate SPAN value.





## 5-3. Simulation Calibration Mode(Calibrate without Test weight)

With this "Simulation Calibration Mode" you can make simple calibration without any "TEST weight" This calibration mode uses "Load cells' max capacity" and "Max Output Rate(mV)", so the weight adjustment degree might be less than "Test weight Calibration".

The guaranteed resolution of this "Simulation Calibration" is 1/3,000.

#### 5-3-1. Simulation Calibration Mode Start





#### 5-3-4. Measure the "DEAD Weight" of Weighing Scale.

dERd	When "DEAD" is displayed, press Then the indicator starts to measure and find optimal "Dead weight value of Scale" automatically
CAL-D	It takes 10sec or 20sec to get the best situation.

### 5-3-5. Input Max. Output (Rated Output Voltage / mV)

rnU	After "mV" is displayed, Check the Rated output value of Load cell. (Refer to the load cell label, or Test Report) .	
2.00000	Ex) Load cell rated output 2.0mV/V	
ЪЯа	If input wrong value, there will display "BAD", please go back to <i>Setting</i> <i>"Capacity of Load Cell".</i> After recheck the label of load cell and retry the process.	
donE	After finishing calculation, calculated "Span value", "DONE" will be displayed.	
0.62923	Now, the Simulation Calibration is done,	
End	Press <b>b</b> key to complete the calibration process.	

In case of multiple pieces of load cells are connected, the rated output will be same as single load cell's. (Because plural load cells are connected with parallel connection, the sum of rated output voltage is same as single load cell's rated output) %Due to some variation between **"State output rate"** and **"Real Output rate"** of load cell, there might be some weight difference after finishing calibration.

If you want to make more precise weighing process, please measure real output rate of load cell and input the measured value.

This Simulation calibration mode uses "Load cells' max capacity" and "Max. Output Rate(mV)", so the weight adjustment degree might be less than "Test weight Calibration". *The guaranteed resolution of this "Simulation Calibration" is 1/3,000.* 

## 5-4. F-FUNCTION Setting

This is the Menu which can set the all of the functions.

5-4-1. Start "SET UP" Mode (Pass Word Not use)



## F-Function List

General Function Setting ("●" Factory default set value)

Weighing Data Save Method selection					
E01	●	0	Non-Save Mode (Weight Data & weighing counter)		
FUI		1	Save Mode (Weight Data & weighing counter)		
			Weight –Back up selection		
E02		0	Normal Mode		
102		1	Weight Back up Mode		
			Motion Band Range setting		
		01	This is set "Steady" acceptable range of weighing part.		
F03	05	ſ	If there is vibration on weighing part, you can set this function and reduce		
105	05	99	the vibration effect on weighing process.		
		55	1 : Weak vibration ~~ 99 : Strong Vibration		
			Zero Tracking Compensation Range setting		
		00	Due to external causes (Temperature, wind, and dust), there will be small		
F04	05	ſ	weight difference, the Indicator will ignore the weight difference and		
		99	display as Zero.		
			Auto Zero Range setting		
	00	00	Within the "Auto Zero" range, weighing part is steady, indicator will display		
F05		ſ	current weight as "Zero"		
		99	If the weighing part is not "Steady", indicator will display current weight.		
			(Auto Zero Range : ± Set value + weight unit)		
			Digital Filter setting		
F06	04	00~40	0 (Weak vibration ) ~ 40 (Strong Vibration)		
	1		Zero key Operation mode selection		
F07		0	Activate only under "Steady" condition		
		1	Always activate		
	Zero key Operation Range selection : (-) value is same to (+)				
		0	Activated within 2% of Max. Capacity		
		1	Activated within 5% of Max. Capacity		
	●	2	Activated within 10% of Max. Capacity		
F08		3	Activated within 20% of Max. Capacity		
		4	Activated within 50% of Max. Capacity		
		5	Activated within 100% of Max. Capacity		
		6	There is no limit of Zero key operation range.		
<b>※</b> CAUTION : If setting over than 10%, The display weight could be over than Load cell					
input signal or Max. Capacity and it may display "CELL-Err" or incorrect weight value.					

	Tare key Operation Range selection : (-) value is same to (+)				
500		0	Activated within 10% of Max. Capacity		
		1	Activated within 20% of Max. Capacity		
FU9	ullet	2	Activated within 50% of Max. Capacity		
		3	Activated within 100% of Max. Capacity		
			"Hold" Mode selection		
	$\bullet$	0	Peak Hold : Measure Max. weight value and hold on display.		
F10		1	Sample Hold : Hold current weight until "Hold Reset"		
		2	Average Hold : Hold average value (Refer F-F50)		
			"STEADY" condition check time setting		
F11	03	00 ∫ 09	During the set time period, estimate weighing part's "STEADY" condition and display. If you set small value, indicator will take "STEADY" fast, if you set value, indicator will take "STEADY" slow. ( 0.5sec per set value)		
			Display Up-Date speed setting		
		1	60/sec		
		2	30/sec		
		3	20/sec		
		4	15/sec		
F12		5	10/sec		
		6	6/sec		
		7	3/sec		
		8	2/sec		
		9	1/sec		
Weight Display selection under "Unpass / OverLoad"condition					
F13		0	Not Display Weight (just "UNPASS" or "-OL-" is displayed)		
115	$\bullet$	1	Display Weight (with a flash)		
Equipment No. setting – ID No.setting					
F18	01	01~99	ID No. setting with No. key. (01~99 settable)		

## ■ Communication Mode Setting

Parity Bit selection Mode										
	٠	0	DATA Bit (8 Bit)	STOP Bit (1 Bit)	Parity Bit (Non)					
		1	DATA Bit (8 Bit)	STOP Bit (1 Bit)	Parity Bit (Odd)					
F30		2	DATA Bit (8 Bit)	STOP Bit (1 Bit)	Parity Bit (Even)					
		3	DATA Bit (8 Bit)	STOP Bit (2 Bit)	Parity Bit (Non)					
		4	DATA Bit (8 Bit)	STOP Bit (2 Bit)	Parity Bit (Odd)					

		5	DATA Bit (8 Bit)	STOP Bit (2 Bit)	Parity Bit (Even)						
		6	DATA Bit (7 Bit)	STOP Bit (1 Bit)	Parity Bit (Odd)						
		7	DATA Bit (7 Bit)	STOP Bit (1 Bit)	Parity Bit (Even)						
		8	DATA Bit (7 Bit)	STOP Bit (2 Bit)	Parity Bit (Odd)						
		9	DATA Bit (7 Bit)	STOP Bit (2 Bit)	Parity Bit (Even)						
			Serial Communicat	tion Speed selection							
		0	2,400bps								
		1	4,800bps								
	•	2	9,600bps								
		3	14,400bps								
F31		4	19,200bps								
151		5	28,800bps								
		6	38,400bps								
		7	57,600bps								
		8	76,800bps	76,800bps							
		9	115,200bps								
DATA Transference Method selection											
		0	Simplex Mode / Stream Mode								
F32	•	1	Duplex Mode / Command Mode								
		2	Print Mode								
	1	"Ch	eck-Sum" detection selecti	on (Under F32-01 settin	ıg, only)						
F34	•	0	Check-Sum Not Use								
		1	Check-Sum Use								
	Unde	er Strea	m Mode select the way tra	ansmit data protocol/fra	ame (basic port)						
F35	•	0	Transmit by Protocol								
		1	Transmit by frame (in case	of using specific utility)							
Cauti	on : In	case o	of "Transmit by frame" 8	under 14,400bps sett under	ing(F31), the speed of						
syste	m will I	be slow									
		DATA	A Transference Mode selec	tion (Under F32-00 setti	ing, only)						
	•	0	Always								
		1	Single time data transference, Whenever the weight is steady over Empty range.								
F36											
		2	Single time data transferer	ice, at first steady point,	over Empty range.						
			Transference, Wheney	ver Print key input	ting only)						
F 27				when use external aller h	ang, only)						
F3/		U	Format 1 (recommended v	when use external display	<i>'</i> )						

		1	Format 2. (Format 1 + ID No.)		
		2	Format 3. (recommended when connecting to PLC or PC)		
3 CAS Format					
			Print Mode selection (Under F32-02 setting, only)		
	•	0	Manual Print : Whenever "Print" key input.		
F38 Auto print or Whene		1	Auto print (at the first Steady point over "EMPTY" range or Whenever "Print" key input.)		
		2	Auto print (Whenever Steady status at over "EMPTY" range or Whenever "Print" key input.)		

## Print Mode Setting

	Weight Unit selection						
		0	Kg				
F41		1	g				
		2	t				
			Print Format selection				
F42		0	Continuous Print - Serial No. and Weight will be printed continuously.				
F42		1	Single Print - Date, Time, S/N, ID No. Weighing Data will be print				
	-		SUB/GRAND Total Data Delete selection				
<b>F</b> 44		0	Not deleted (= manual Delete mode)				
F44		1	Automatically DeletedAfter print out SBU/GRAND Total.				
		Ра	aper Withdraw Rate setting (After SUB/GRAND Total Print)				
F45	03	3 00~09 Whenever set value increased as 1, then 1 line will be added.					
	Paper Withdraw Rate setting (After Continuous/Single Print)						
F46	03	00~09	Whenever set value increased as 1, then will be added.				
			Printing Language Selection				
F 4 7		0	KOREAN				
F47		1	ENGLISH				
			Minus(-) symbol Print selection				
E 40		0	Print minus(-) symbol, if the weight is minus(-).				
F49		1	Ignore minus(-) symbol				
	-	-	Set time of "Average Hold"				
F50	03	00~9	When setting "Average Hold", set the time. (unit : sec) «Automatic Hold Rest , After set time.				

#### **Other Setting Mode EMPTY Range setting** You can set "EMPTY" Range. F80 Ex) "0" setting : When Net Zero, "Zero" status lamp is ON. 10 "200" setting : Under "200", "Zero" Status lamp is ON. TIME(H,M,S) Check / Change (every 24Hours) F90 Check Current DATE data or you can Change to new date TIME Check / Change F91 Check Current TIME data or you can Change to new time SETUP Mode Password Key Setting / Change Setting the password 1) When "1" shows input the 2) When "2" displays input the password with 4 characters. same password again. Change the password P-!!, F95 1) If "P-W" displays 2)If "1" displays input the 3)If "2" displays input the input current password new password . new password again. **Deactivate Lock setting** If you set the password including key, it is unlocked. When setting password you cannot start "SETUP" mode without password, do not forget your password. **Program & Hard ware Version Check** Check the Program & Hard ware version F98 Ex) "100 1.04" means H/W : ver.1.00 & S/W : ver.1.04

### 5-5. Test Mode

Before starting the TEST mode, please remove operating devices.



#### 5-5-1. Analog Check Mode

Under this mode, you can check analogue value to real digital value through Display. The last digital value can be fluctuated



## 5-5-2. Key / Digital input Test Mode

Under this mode, you can test Key input and Digital Key input test



#### 5-5-3. Serial Interface Test Mode.

This is the mode to check RS232C port.

<b>E</b> key 4 times	$\rightarrow \overset{\text{PRINT}}{\blacktriangleright} \text{key} \rightarrow \overset{\text{HOLD}}{\blacktriangleright} \text{key}$
RS-232C RxD TxD GND	Short between Rxd & Txd of Indicator terminal.
[Ornl	Enter the RS232C test mode and "COM1" is displaying, then press
PRSS	Displaying "PASS" is that the port works well.
UNPASS	Displaying "UNPASS" means that the port 's IC chip has a problem. Contact your seller or the main office

**%** If you send "Testing protocol" from PC to Indicator, at the normal operation Display will blink.

## **6.** INTERFACE

#### 6-1. Serial Interface

#### 6-1-1. Serial Interface (RS-232C)



RxD	3
TxD	2
GND	5



### 6-1-2. Current Loop



Serial communication interface is sensitive to electric noise. Install isolated place from Power cable or other electric cables and wires, and please use shielded cable for better performance.

#### 6-1-4. Data Format

1. Data Format1 : ID Number is not be transferred.(Refer "FUNCTION 37/F67-00" setting)

Header 1		Header	2		Ľ	Data Byte 7 byte	, Ur	nit		
	,		,	+/_			k	g	CR	LF
						11				

Header1	Header2
OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)
ST : STEADY	GS : when setting TARE
US : UNSTEADY	

2. Data Format2 : ID Number + Data Transference (Refer F-function 37-01, F18)

ID Number	Header 1		Head	der 2			Dat 7	a By byte	yte Ə	Ui	nit		
,		,			,	+/_		1/		k	g	CR	LF
							7						

Header1	Header2
OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)
ST : STEADY	GS : when setting TARE
US : UNSTEADY	

#### 3. Data Format3 : ID Number + State (F37-03 setting)

STX	ID N	lumber	State 1	Fixed by		yte	Data Byt 7 byte	е	Decimal Point ETX				
02h					"W"	+ <sub>/_</sub>			" <b>P</b> "		03h		
								Fi	 ked by	/te			
		ŀ	leade	r1			Header2						

Header1	Header2
O : OVER	G : Gross weight
S : STEADY	N : Net weight
U : UNSTABLE	

SI 300

#### SI 300

Header 1	He	ader 2	Nu	ID mber	Data B 8 by	Byte <sup>te</sup> Space	e Uı	nit		
	,		,		, //		k	g	CR	LF
LAMP DIS	PLAY			Lamp Display						
Bit 7	Bit 6	Bi	t 5	Bit 4	Bit 3	Bit 2	Bi	t 1	E	Bit O
1	0		1	1	1	1		1		1
1	STEADY		1	Hold	Print	Gross Weight	TA	RE	Z	ERO
			Неа	der1	Head	er2				

#### 4. CAS Format (22byte)

Header1	Header2
OL : OVER LOAD	NT : GROSS weight
ST : STEADY	GS : Net weight
US : UNSTEADY	

#### 6-1-5. Command Mode (F32-01 setting)

Under "Command Mode", Indicator will recognize the receipt of Order based on 02h(Header) and 03h(END) signal, and transfers ACK/ NAK).



\*\*Although wrong value is transmitted, the communication format is matched, then ACK is transmitted.

## **Read Command**

	1.Current Weight data					
ASCII : STX ID(2Byte	e) RCWT ETX HEX: 02 30 31 52 43 57 54 03					
	STX ID RCWT State1(1byte) State2(1byte) P decimal point(1byte)					
	+/-(1byte) Current weight(7byte) unit(2byte) ETX					
SI 300 response	State1 : O(Over load) , S(Steady), U(Unsteady)					
	State2 : N(Net weight), G(Gross weight), P+No. : decimal point					
	number					
Ex) Steady(S), TARE	not used(N), 0.000kg					
	State1, State2, Decimal point					
STX ID R C 02h 30h 31h 52h 43	W T S N P 3 + 0 0 0 0 0 0 0 0 k g ETX h 57h 54h 53h 4Eh 50h 33h 2Bh 30h 30h 30h 30h 30h 30h 6Bh 67h 03h					
	2. Indicator memory data					
ASCII : STX ID(2Byte	e) RCWD ETX <b>HEX :</b> 02 30 31 52 43 57 44 03					
	STX ID RCWD P decimal point (1byte)DATE(6byte) TIME(6byte) the					
SI 300 response	no. of weighing (6byte) +/- TARE(7Byte) +/- current					
	weight(7byte) unit(2byte) ETX					
Ex) DATE : Aug 12 <sup>th</sup> ,	2009, TIME : 12:00:00, the no. of weighing : 10, TARE : 2.000kg, current					
weight : 3.000kg						
	decimal point					
STX ID. R	C W D P 3 0 9 0 8 1 2 1 2 0 0 0 0					
02h 30h 31h 52h 4	3h 57h 44h 50h 33h 30h 39h 30h 38h 31h 32h 31h 31h 30h 30h 30h 30h					
0 0 0 1	0 + 0 0 0 2 0 0 0 + 0 0 0 3 0 0 0 ETX					
30h 30h 30h 30h 31h	30h 2Bh 30h 30h 30h 32h 30h 30h 30h 30h 2Bh 32h 30h 30h 30h 30h 30h 03h					
3. Grand Total data						
ASCII : STX ID(2Byte	e) RGRD ETX HEX: 02 30 31 52 43 57 44 03					
ST 300 response STX ID RGRD P decimal point (1byte) the no. of weighing (6byte)						
Accumulated weight(10byte) unit(2byte) ETX						
Ex) the no. of weighing : 10 , Accumulated Weight : 10.000kg						
	decimal point					
STX ID R G						
02h 30h 31h 52h 47h	52h 44h 50h 33h 30h 30h 30h 30h 31h 30h 30h 30h 30h 30h 30h 30h 30h 30h 30					

4.Finished Weight data				
ASCII : STX ID(2Byte) RFIN ETX HEX: 02 30 31 52 46 49 4E 03				
SI 300 response STX ID RFIN P decimal point(1byte) +/- Finished weight(7byte) ET				
Ex) Finished weight : 2.000kg decimal point				
STX ID R F I N P 3 + 0 0 0 2 0 0 0 ETX				
02h 30h 31h 52h 46h 49h 4Eh 50h 33h 2Bh 30h 30h 30h 32h 30h 30h 30h 03h				
5. Current time Data				
ASCII : STX ID(2Byte) RTIM ETX         HEX: 02 30 31 52 54 49 4D 03				
SI 300 response STX ID RTIM Current Time(6byte) ETX				
Ex) Time : 12:00:00				
STX ID R T I M 1 2 0 0 0 0 ETX				
02h 30h 31h 52h 54h 49h 4Dh 31h 32h 30h 30h 30h 03h				
6. Current date Data				
ASCII : STX ID(2Byte) RDAT ETX         HEX : 02 30 31 52 44 41 54 03				
SI 300 response STX ID RDAT Current Date(6byte) ETX				
Ex) Date : Aug 12 <sup>th</sup> ,2009				
STX ID R D A T 0 9 0 8 1 2 ETX <sup>(</sup>				
02h 30h 31h 52h 41h 41h 54h 30h 39h 30h 38h 31h 32h 03h				
7. Tare data				
ASCII : STX ID(2Byte) RTAR ETX         HEX : 02 30 31 52 54 41 52 03				
STX ID RTAR P decimal point(1byte) +/-(1byte) TARE value(7byte) ETX				
Ex) TARE : 2.000kg decimal point				
STX ID R T A R P 3 + 0 0 0 2 0 0 0 ETX				
02h 30h 31h 52h 54h 41h 52h 50h 33h 2Bh 30h 30h 30h 32h 30h 30h 30h 03h				

Recommended Interval of READ COMMAND is min.60ms, 70ms is

recommended, under 9600bps setting.

Min.60ms is required between each Read Command(under RCWD)

Min. interval is changed when data's length & speed are changed.

Min Interval : 20ms under 2400bps(RCWD)

Min Interval : 40ms under 115200bps (RCWD)

## ■Write Command

	Zero (same as "ZERO" key)					
ASCII : STX ID(2Byte)	) WZER ETX	HEX: 02 30 31 57 5A 45 52 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	TAR	RE				
ASCII : STX ID(2Byte)	) WTAR ETX	HEX: 02 30 31 57 54 41 52 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	TARE I	reset				
ASCII : STX ID(2Byte)	) WTRS ETX	HEX: 02 30 31 57 54 52 53 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	HOL					
ASCII : STX ID(2Byte)	) WHOL ETX	HEX: 02 30 31 57 48 4F 4C 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	HOLD	reset				
ASCII : STX ID(2Byte)	) WHRS ETX	HEX: 02 30 31 57 48 52 53 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	PRI	INT				
When transfer for	ormat, "F46 : plus line" a	and "F34 : checksums are not applied.				
ASCII : STX ID(2Byte)	) WPRT ETX	HEX: 02 30 31 57 50 52 54 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	PRINT gra	and total				
ASCII : STX ID(2Byte)	) WGPR ETX	HEX: 02 30 31 57 47 50 52 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
	Delete gra	and total				
ASCII : STX ID(2Byte)	) WGTC ETX	HEX: 02 30 31 57 47 54 43 03				
SI 300 response	normal: STX ID ACK ETX	X error: STX ID NAK ETX				
Date setting						
ASCII : STX ID(2Byte) WDAT current DATE (6byte) ETX						
Ex) Date : Aug 12 <sup>th</sup> ,2009						
STX ID	W D A T (	090812ETX				
02h 30h	31h 57h 44h 41h 54h 30	30h 39h 30h 38h 31h 32h 03h				



## Command Mode Example

### **READ COMMAND**

Ex.) Current Weight Command(RCWT), ID No.: 01, Current Weight: 7,000kgP.C Read Command Format (STX ID NO. RCWT ETX) "Check-sum" not used.



2) When PC requests to Indicator, Format(STX ID RCWT ETX) CHCEK SUM is used.



#### WRITE COMMAND Ex) SP1 Setting Command, ID No: 01, New SP1 Set value: 0.600kg 1) PC Write command format (STX ID WPR1 000.600 ETX) "CHECK SUM" not use. PC transmits to SI300 STX ID 2 w Т м 1 0 0 0 0 I ETX 31h 57h 54h 49h 4Dh 31h 32h 30h 30h 02h 30h 30h 30h 03h SI300 **Response to PC** STX ID ACK ETX STX ID NAK ETX 02h 30h 31h 15h 03h 02h 30h 31h 06h 03h

Normal operation

SI 300

Incorrect operation

1) PC Write command format (STX ID WPR1 000.600 ETX) "CHECK SUM" use.



All Read/Write command must be use "HEX CODE"..

How to Calculate Check sum.

- Sum the value from "STX" to "ETX" and converts to ASCII(2byte) and transfer.

Convert the Sum value(HEX) to ASCII and transmit(28byte) .

ex) The sum HEX value from STX to ETX(02,30,31,52,43,57,54,03) is 1A6h.

Then, divide 1A6h by 100h(1A6h/100h). the rest of result is A6h.

Calculated remainder value is A6h, then convert A6h to ASCII, 41(A), 36(6), and transfer.

## 6-2 Serial Print (F32-02 setting) – RS-232 Serial Interface.

It can be connected with all kinds of Serial interface printer, but the printing format is already programmed and fixed with SE7200/7300 model.

#### 6-2-1. Printing Format

Using the RS-485 or 422 interface, please use convertor and converts to RS-232 and connect with Serial printer.

If you use RS-232 serial interface, connect directly without any convertor.

#### English Format (F47-01)

DATE :	2009-05-10
TIME :	18:00:10
COUNT	WEIGHT
1	+ 1.330kg
2	+ 5.350kg
3	+ 1.380kg
4	+ 2.330kg

	10.00.10
COUNT	WEIGHT
2	+ 5.350kg
=======================================	
DATE :	2009-05-10
TIME :	18:00:10
COUNT	WEIGHT
3	+ 1.280kg
L	

DATE :

TIME .

**Continuous Print Format(F42-00)** 

TOTAL	
DATE : TIME :	2009-05-10 18:00:10
COUNT : TOTAL WEIGHT :	10 258.145kg
TOTAL DELE	======== TE

Single Print Format(F42-01)

2009-05-10

18.00.10

**Grand Total Print** 

(Grand Total Print delete setting, F44-01)

**%** Under "F01-01" setting, the current weight is saved and print out.

## 7. Error & Treatment

## 7-1. Load Cell Installation

Error	Cause	Treatment	Remarks
Weight Value is unstable	<ol> <li>Load cell broken</li> <li>Load cell isolation         resistance error         3) Weighing part touches         other devices or some         weight is on the weighing         part         4) Summing Board Error     </li> </ol>	<ol> <li>Measure         <ul> <li>input/output resistance</li> <li>of Load cell.</li> </ul> </li> <li>Measure Load cell         <ul> <li>isolation resistance</li> </ul> </li> </ol>	<ol> <li>Input Resistance of "EXC+" and "EXC-" is about 400Ω ±30</li> <li>Output Resistance of "SIG+" and "SIG-" is about 350Ω ±3.5</li> <li>Isolate Resistance is more than 100MΩ</li> </ol>
Weight Value is increased regular rate, but not return to "Zero"	<ol> <li>Load cell Error</li> <li>Load cell connection Error</li> </ol>	<ol> <li>Check Load cell</li> <li>connection</li> <li>Measure Load cell</li> <li>Resistance</li> </ol>	
Weight Value is increased to under Zero	Load cell Output wire (SIG+, SIG-) is switched	Make wire correction	
"UN PASS" display	Load cell broken or Indicator connection Error	Load cell Check Load cell connection Check	
	weight is on the load cell.	Load cell	
"OL" or "UL" display(Over Load)	<ol> <li>Load cell broken or</li> <li>Indicator connection Error</li> <li>Loading over than Max.</li> <li>Capacity</li> </ol>	<ol> <li>Load cell Check</li> <li>Load cell connection</li> <li>Check</li> <li>Remove over loaded</li> <li>weight</li> </ol>	

## 7-2. Calibration Process

Display	Cause	Treatment
ErrOl	When Max.capacity/digit value is over 20,000	Re-input the Max. Capacity, less than 20.00
		(Max. Capacity / Digit)
Feeny	Standard weight value is over than Max.	Re-input Standard weight value with
2	Capacity	Number keys, under Max. Capacity
	Standard weight value is less than 10% of	Re-input Standard weight value with
Err05	Max Capacity	Number keys, more than 10% of Max.
		Capacity
		Check standard weight's weight with set
	1. Amp. Gain is too big	value.
Err06	2. Sig+ and Sig- wire connection error	If there is difference between set value
	3. Test weight is not loaded	and real weight, please re-input the value
		(set value is too small)
		Check standard weight's weight with set
	1. Amp. Gain is too small	value.
ErrO7	2. Sig+ and Sig- wire connection error	If there is difference between set value
	3. Test weight is not loaded	and real weight, please re-input the value
		(set value is too big)
Err08	Under "F-function" model, set value is	Check the correct value and re-input
	"N.A"	
	When there is continuous vibration on the	- Find vibration cause and remove
Err-A	weighing part,, indicator cannot process	- Load cell check
,	calibration any more.	- Load cell cable and connecting
		condition check

Display	Cause	Treatment
		1. Under "TEST" mode 1, check analogue
"EELL- Er" or "DUEr"	<ol> <li>Load cell Error</li> <li>Load cell cable Error</li> <li>Load cell connection Error</li> <li>A/D Board Error</li> <li>A/D Board Error</li> <li>If Analogue value         <ul> <li>is over 1,040,000.</li> <li>When weigh "-" value,</li> <li>If it is over set max capa, "OVER"             <li>is displayed.</li> <li>Ex) Even though set max capa is</li></li></ul></li></ol>	<ul> <li>value. If you cannot get any analogue value or there is no change although adding load, please check load cell, load cell cable, connection conditions first.</li> <li>2. Replace another load cell, and check the indicator condition. If you have same problem, please replace new indicator and check A/D board error.</li> <li>3. Try to connect the indicator's A/D with the other indicator.</li> </ul>
		terminal.
"UNPR55"	<ol> <li>Power is ON, when some materials are on weighing part.</li> <li>W Under "Normal Mode", if there are more than 20% loading of Max. capacity, "Un-Pass" display will be appeared and indicator will stay until removing the load.</li> <li>Setting Back-up mode it can memory empty value, and it becomes set value without displaying" Un-pass")</li> </ol>	<ol> <li>If you set "Normal Mode", please check weighing part empty or not before turn on the power. If there are some materials in/on weighing part, please remove those materials and turn on the power.</li> <li>Please try to set F02-01(Back-up) mode so that the indicator can remember first empty value.</li> </ol>
"SEL"	When Power is on, "SET" displays. It means EEPROM has some problem.	Please contact the distributor or Head
"HALL"	H/W has some problem.	Unice.
"E-Err"	The dead Battery	

## 7-3. Digital Weighing Indicator

\* Under **"[ELL-Er"**, Zero key, Tare key, Hold key and print key will not be activated.

#### WARRANTEE CETIFICATION

This product is passed "Sewhacnm's strict quality test.

If there is defect of manufacturing or abnormal detection within warrantee period,

please contact our Agent or Distributor with this Warrantee certificate.

Then, we will repair or replace free of charge.

#### WARRANTEE CLAUSE

# 1. The Warrantee period, we can guarantee, is one(1) year from your purchasing date

#### 2. Warrantee Exception Clause

- Warrantee period is expired.
- Any kinds of Mal-function or defection caused by Modification or Repair without Sewhacnm's permission.
- Any kinds of Mal-function, Defection, or External damage, caused by operator
- Any kinds of Mal-function, Defection, caused by using spare part from Non-Authorized Distributor or Agent.
- Any kinds of Mal-function, Defection, caused by not following Warnings or Cautions mentioned on this manual.
- Any kinds of Mal-function, Defection caused by "Force Majeur", like Fire, Flood.
- Without presentation of this "Warrantee Certification".
- 3. Other
  - Any kinds of "Warrantee Certification" without authorized Stamp is out of validity

#### SEWHACNM Co.,Ltd.

#504-302, 397, Seokcheon-ro, Ojeong-gu,

Bucheon-si, Gyeonggi-do, Korea

#### Made in KOREA

Website : http://www.sewhacnm.co.kr ,

Email : <u>sales@sewhacnm.co.kr</u>

Product	Digital Weighing Indicator		
Model	SI 300		
Serial No.			
AUTHOR STAM	IZED P		